

FIG.1A




FIG.1B



Super P(conductive agent) powders are conglomerated

FIG.2




FIG. 2 is a schematic diagram illustrating the effect of surfactant on active material. The diagram shows three shaded circles representing active material on the left. An arrow points to the right, where three similar circles are shown, each with six lines radiating from its center, representing the addition of surfactant. One of these circles is labeled "Surfactant" with an arrow pointing to one of the radiating lines.

FIG.3A

(PRIOR ART)




FIG.3B




FIG.3C




FIG.4




FIG.5A




FIG.5B




FIG.6A




FIG.6B




FIG. 7A




FIG. 7B




FIG.8A




FIG.8B




FIG.9A




FIG.9B




FIG.10




FIG.11




FIG.12




FIG.13




FIG.14




FIG.15




FIG.16

